

# The Mysterious 57.07 error in the HP LJ 46xx

The 57.07 fan error in the LaserJet 4650 is unmentioned in the manuals. It indicates the failure of third fan of this model and the 4610. The 4600 has just two fans and does not get this code.

In the course of our experiments to verify the fan assignments for these printers, we noticed that part numbers and reference designations were inconsistent, and that there were subtle differ-

ences in the error codes which were not reflected in the manuals. Armed with the corrected information below, you will be able to confidently diagnose and repair fan errors in the 4600 series.

—Dennis Kosterman

©2007 Liberty Parts Team, Inc.

HP 4600, 4610/50 57 Error: Corrected Number Assignments				
4600 Error	4610/4650 Error	Fan	Location	Part Number
57.30	57.03	Cartridge	Top left	RH7-1491
57.40	57.04	Formatter	Top rear	RH7-1490
N/A	57.07	Power Supply	Bottom	RH7-1607